

TUBA

BRONZE SERVICE - \$45.00 + GST (Total: \$51.75)

1. Wipe body and slides
2. Inspect and check all parts are working
3. Check valves and slides
4. Tested

SILVER SERVICE - \$150.00 + GST (Total: \$172.50)

1. Wash body, slides, caps and mouthpiece
2. All valves are cleaned and oiled
3. All slides are cleaned and greased
4. Replace felts where necessary
5. Replace waterkey corks where necessary
6. Tested

GOLD SERVICE - \$225.00 + GST (Total: \$258.75)

1. Extra cleaning and polishing on body, slides, caps and mouthpiece
2. All valves are oiled
3. All slides are cleaned and greased
4. Replace felts where necessary
5. Replace waterkey corks where necessary
6. Free all stuck slides
7. Tested

EXTRA SERVICES

- | | |
|-------------------------------|--------------|
| 1. Remove dents | POA |
| 2. Soldering | \$30.00 |
| 3. Valves lapped / burnishing | \$15.00 each |
| 4. Patching | \$30.00 each |
| 5. Straighten bent body | \$30.00 |
| 6. Slide realignment | \$30.00 |
| 7. Free stuck slide | \$20.00 |

All stuck mouthpieces are freed - No Charge